



Units 5&6 The Gryphon Ind Park,
Porters Wood
St Albans. AL3 6XZ
01727 867747
www.car-clinic.info



Hertfordshire Used Cars
1 Priory Lane
Little Wymondley
Hitchin
Hertfordshire
SG4 7HE

Invoice 91236
Invoice Date:
Account No: HER861
Order Ref:
Date of Work: 27/11/2025
Payment Date:
Payment Method:

Registration	Make & Model	Chassis Number	Engine CC	Mileage
EJ66 GDE	Vauxhall Viva SI	W0lde6e77hc733263	999	45427
Engine No	Engine Code	Key Code	Date Reg	Paint Code
L5Q162040083L5Q	B10XE		31/10/2016	M

- Carry Out Full Service
- Check Cambelt Schedule (If Required)
- Brake Fluid Age ?
- Coolant Age/Schedule ?
- Gearbox Oil Change Required ?

MOT	Qty	Status
Carry out MOT Test	1	Pass

Parts	Part No.	Qty	Unit	D	Sub Total
Wipers		1	23.07		23.07
Rear Wiper		1	6.94		6.94
Oil & Filter Disposal	OIL	1	4.50		4.50
Oil Filter	OF	1	16.13		16.13
Air Filter	AF	1	30.08		30.08
Pollen Filter	PF	1	21.65		21.65
Spark Plugs	SP	3	20.57		61.71
Sundries - Grease/ Oil Etc	SUN	1	4.50		4.50
Oil System Flush And Cleaner	FLUSH	1	8.50		8.50
Screen Wash	SCR	1	1.50		1.50
Fuel Injection Treatment	INJ TREATMENT	1	10.00		10.00
Sump Sealing Washer	SUM	1	1.50		1.50
Brake Cleaner	BRAKE	1	1.50		1.50
0w20 Synthetic Engine Oil	OIL20	4	14.00		56.00
Numberplates		1	25.00		25.00
Tpms Sensor		1	30.00		30.00





Units 5&6 The Gryphon Ind Park,
Porters Wood
St Albans. AL3 6XZ
01727 867747
www.car-clinic.info



Hertfordshire Used Cars
1 Priory Lane
Little Wymondley
Hitchin
Hertfordshire
SG4 7HE

Invoice 91236
Invoice Date:
Account No: HER861
Order Ref:
Date of Work 27/11/2025
Payment Date:
Payment Method:

Labour	Qty	Unit	D	Sub Total
Carried Out Full Service	2	95.00		190.00

VAT Reg No. 738 1978 88

Bank Details For BACS Payments
St Albans Car Clinic
Sort Code 20-74-09
Account Number 10347795

Labour	190.00
Parts	302.58
SubTotal	492.58
VAT (20%)	98.52
MOT	54.85
Total	645.95
Balance	645.95

